



Technical Bulletin: 7

Revision: 1

Razor International Pty Ltd, Campbellfield VIC
service@razorinternational.com
1300 555 865

Controller Upgrade (ECAP14A)

Affected Product: ECAP14, RMC Controllers

Razor International has made several upgrades on the controller housing listed below


1. 304 Stainless steel mounting plate added
2. Secondary outer seal added
3. Stainless steel cover return spring added


The upgrades have been implemented to improve the longevity of controller housing and watertight integrity.

Refer separate page 2 for new mounting plate drill template.

Always use mounting plate and seal on new installation.

1. **THESE ADDITIONAL COMPONENTS SHOULD NOT BE REMOVED OR SUBSTITUTED AS IT MAY VOID WARRANTY.**
2. **ALSO, IT MAY VOID WARRANTY IF THE PLUGS ON THE CONTROLLER ARE CUT**





Note: As all printers may not print to scale, ensure template dimensions reflect the dimensions above

Page 2 of 2