



# Technical Bulletin:

## Revision: 1

Razor International Pty Ltd, Campbellfield VIC

[service@razorinternational.com](mailto:service@razorinternational.com)

1300 555 865

## AP Controller & Remote Upgrade (CII)

**Affected Product:** ECAP Controller & Remote

ECAP controller set up (Previous version)	CII Set up (Current version)
<p><b>Controller :</b> The ECAP Controller product span is between 2014-2020. This controller is now obsolete.</p> <p><b>Remote :</b> The Remote is still purchasable for replacements and missing remotes for previous systems.</p>	<p><b>Controller :</b> Razor International has made upgrades on the controller assembly listed below:</p> <ol style="list-style-type: none"><li>1. More durability material used</li><li>2. New Keypad</li><li>3. New PCBA</li></ol> <p>The upgrades have been implemented to improve:</p> <ol style="list-style-type: none"><li>1. Life span of controller housing</li><li>2. Keypad Activation Reliability</li></ol> <p><b>Remote :</b> Razor International has made upgrades on the remote assembly listed below:</p> <ol style="list-style-type: none"><li>1. More durability material used</li><li>2. User-friendly operation</li><li>3. Bluetooth enabled with controller PCBA</li><li>4. Phone app accessibility</li></ol>
<p><b>Image of Previous Set up includes</b></p> <ul style="list-style-type: none"><li>• ECAP Controller</li></ul>	<p><b>Upgraded Set up (P/N: CII-ER) includes</b></p> <ul style="list-style-type: none"><li>• CII controller</li><li>• 3 button remote</li></ul>